

Inspection Photos

Operator: Petrox Resources

API: 05-007-06277

Date: 11/06/2018



Photo 1. View of the project area from southeastern corner facing center. Interim reclamation is not conducted.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Little desirable vegetation on slope. Russian thistle (*Salsola tragus*) debris up to three feet tall, growing along the outer edges of the working area.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of expanded disturbance in the northwestern project area. Needs reclamation.



Photo 5. View of soil and sediment deposition up to 2.5 feet deep, around the base of trees from soil transport from the project area, in the northwestern project area.



Photo 6. View of unstabilized soils and sediment deposition around trees in the northwestern project area.



Photo 7. View of unstabilized soils, erosional channel approximately 2 feet wide and 1.5 feet deep, and sediment deposition/transport in the northwestern project area.



Photo 8. View of the western project area from the northwestern edge of the working area. Trench approximately 3 feet deep along the edge of the working area.



Photo 9. View of musk thistles (*Carduus nutans*) within the western project area.



Photo 10. View of the western cut-slope from the northwestern corner facing southward.



Photo 11. View of erosional channel forming from stormwater run-on within the western cut-slope.



Photo 12. View of the southern project area from the southwestern corner facing eastward. Cut-slope is not stabilized.