

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/29/2018

Submitted Date:

12/04/2018

Document Number:

679300021**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
306735 _____ Graber, Candice (Nikki) _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

2 Number of Comments
1 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|--------------------------|---------|
| Inspections, All | | cogccinspection@pdce.com | |
| Oakman, Kari | | kari.oakman@state.co.us | |
| Axelson, John | | john.axelson@state.co.us | |
| Longhurst, Mark | | Mark.Longhurst@pdce.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 290623 | WELL | SI | 07/01/2018 | OW | 123-25173 | VIEFHAUS 43-29U | EI |

General Comment:

COGCC inspection of produced water vault removal pursuant to the Matt #1 Administrative Order on Consent (AOC) order no. 1V-678 item #6. PDC notified COGCC of planned start date of 11/26/2018, inspection occurred on 11/29/2018, there were no operator or contract environmental personnel on location at the time. Vault and all other equipment had been removed and hauled from location area has been graded and is ready for reclamation

Inspected Facilities

Facility ID: 290623 Type: WELL API Number: 123-25173 Status: SI Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Produced water vault removed. ite has been backfilled, no oily waste stockpiled on location.

Corrective Action: The Operator shall submit a Form 27 Site Investigation and Remediation Workplan for the removal of a buried/partially buried produced water vessel in accordance with Rule 905.b. The Form 27 Workplan may be submitted with the excavation and site assessment results, but should be submitted no later than 90 days from the Spill Report Date in order to resolve this release.

Date: 02/27/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 679300022 | Site Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664212 |