

# Construction and Stormwater Inspection

November 28, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 458787

Inspection Document #: 682404235

Arapahoe County, CO

NWSW Section 19 T4S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Lussing Trust  
Location ID: 458787



**Photo 1.** Photo taken from the entrance of the location off Watkins Road, facing Southeast. Photo illustrates paved entrance into the location. Operator in process of stabilizing the main access road- see following photo.



**Photo 2.** Photo taken from the entrance of the location, facing East. Photo illustrates the Operator is in process of stabilizing the main access road with road base. Filtrexx wattle BMP was observed throughout the entire perimeter of the location in conjunction with other BMPs. Note: Operator has stored equipment between the main access road and the location. Operator is responsible for reclaiming all disturbances associated with oil and gas disturbance.



Inspection Photos  
Location Name: Lussing Trust  
Location ID: 458787



**Photo 3.** Photo taken of the disturbance area between the main access road and the location, facing West. Operator is responsible for reclaiming all disturbances associated with oil and gas disturbance.



**Photo 4.** Photo taken from the northwestern perimeter of the location, facing South. Filtrexx wattle BMP has been installed throughout the entire perimeter of the location in conjunction with other BMPs.

Inspection Photos  
Location Name: Lussing Trust  
Location ID: 458787



**Photo 5.** Photo taken from the northwestern perimeter of the location, facing East. Operator in process of stabilizing the well pad.



**Photo 6.** Photo taken from the northwestern perimeter of the location, facing Southeast. See comments under Photo 5.



Inspection Photos  
Location Name: Lussing Trust  
Location ID: 458787



**Photo 7.** Photo taken from the southwestern perimeter of the location, facing East. Photo illustrates the topsoil stockpile that has been temporarily stabilized with equipment tracking.



**Photo 8.** Photo taken from the northeastern perimeter of the location, facing Northeast. Photo illustrates a sediment trap installed with a stabilized outlet.



Inspection Photos  
Location Name: Lussing Trust  
Location ID: 458787



**Photo 9.** Photo taken from the outlet of a culvert, facing West. Stormwater is directed to the stabilized sediment trap.



**Photo 10.** Photo taken from the northern location, facing West. Photo illustrates two sets of ditch BMPs which are directed to the stabilized outlet.