

Inspection Photos

Operator: BP Production

API: 05-067-09442

Date: 11/9/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northwestern project area from the northeastern corner facing southwestward. Revegetation is progressing with grasses such as sand dropseed (*Sporobolus cryptandrus*), western wheatgrass (*Pascopyrum smithii*), and crested wheatgrass (*Agropyron cristatum*). Cobble run-down is filling with sediment and will soon require maintenance.



Photo 3. View of the eastern project area from the northeastern corner facing southeastward.



Photo 4. View of the southwestern project area from the northwestern corner facing southeastward.



Photo 5. View of road surface maintained in good repair.