

Inspection Photos

Location Name: Kinzer 23-3B, C, D Vault Removal

Facility ID: 251612



Photo 1 – Excavation area, partially backfilled after vault removal.



Photo 2 – Hydrocarbon impacted soil along edge of excavation.

Inspection Photos
Location Name: Kinzer 23-3B, C, D Vault Removal
Facility ID: 251612



Photo 3 – Partially backfilled excavation area with impacted soils.



Photo 2 – Stockpiled soils on western side of facility.