

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2018

Submitted Date:

12/07/2018

Document Number:

688800383**FIELD INSPECTION FORM**
 Loc ID 424701 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 34725Name of Operator: GOSNEY & SONS INCAddress: P O BOX 367City: BAYFIELD State: CO Zip: 81122**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**21 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Barnett, Matt		mattb@gosneyco.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424697	WELL	PR	06/01/2012	GW	067-09866	KELSALL 33-7 4-1	EI
428042	WELL	PR	06/01/2013	GW	067-09880	KELSALL 33-7 4-4	EI
428043	WELL	PR	10/02/2012	GW	067-09881	KELSALL 33-7 4-2	EI
428044	WELL	PR	05/29/2013	GW	067-09882	KELSALL 33-7 4-3	EI

General Comment:

On December 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gosney and Sons Inc. Kelsall 33-7 #4-1. For the most recent field inspection report of this facility, please refer to document #685302912.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Tank battery sign mounted to handrail on stairs.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Well head number stenciled on each well head.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Tanks have labels and placards.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Well signs mounted to separator buildings.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Oil containers, pipes, and fittings stored at pump jacks.			
Corrective Action:	Comply with Rule 603.f.			Date: 01/07/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Stained soil near prime mover exhaust.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 01/07/2019
Lube Oil	WELLHEAD	<= 1 bbl		
Comment:	Stained soil around base of #4-1 and #4-2 wellheads.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 01/07/2019
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Lube oil leak below prime mover on #4-3 pump jack.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 01/07/2019

In Containment: No

Comment: ☒ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Perimeter fencing w/ cattle gaurd.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Jersey barriers next to separators.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 3		
Comment:	#4-3 pump jack was dismantled during this inspection.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 3		
Comment:	Natural gas engines.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Telemetry equipment		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	#4-3 and #4-4 wells.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:	Two steel buildings with two separators each.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		37.136842,-107.613934
Comment:	Northern AST.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		37.136797,-107.613936	
Comment: Southern AST.						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities

Facility ID: <u>424697</u>	Type: <u>WELL</u>	API Number: <u>067-09866</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>428042</u>	Type: <u>WELL</u>	API Number: <u>067-09880</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>428043</u>	Type: <u>WELL</u>	API Number: <u>067-09881</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>428044</u>	Type: <u>WELL</u>	API Number: <u>067-09882</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Ditches	Pass	Compaction	Pass			
Berms	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Drip pot at truck load out.
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On December 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gosney and Sons Inc. Kelsall 33-7 #4-1. For the most recent field inspection report of this facility, please refer to document #685302912. Similar issues with stained soil and storage of containers were noted on inspection document #685302440.	hughesjo	12/07/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800384	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668065