

FORM  
INSPRev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2018

Submitted Date:

12/07/2018

Document Number:

690100912**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Maclaren, Joe 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
KPK		cogcc@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459299	SPILL OR RELEASE	AC	11/29/2018		-	SPILL/RELEASE POINT	EG

**General Comment:**

Engineering integrity inspection performed on December 4th, 2018 in response to initial form 19 spill report Doc #401853588 received by COGCC on 11/28/2018 that outlines: A contractor for Extraction was boring a new line under KPK's consolidation flowline (currently shut-in due to line being stung east of release) and an abandoned flowline, when they encountered a historical release via drill cuttings and tie in access. The contractor working for Extraction is currently finishing the installation of their new pipeline and clearing enough room in order for KPK to commence removing the historically impacted soil. There are no live lines in the area and the only active line was flushed before this release was discovered. Details of the observations made during this field inspection are available in the flowline section of this report. Photos uploaded.

**Inspected Facilities**

Facility ID: 459299 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

**Flowline**

#1	Type: Non-Well Site	2 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: \_\_\_\_\_ Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: Yes Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: COGCC Inspector observed (2) flowlines exposed in the excavation/ remediation area; (1) historically abandoned 8" carbon steel flowline being used as a conduit for a new 4" HDPE slipline being stung east of the release area; and (1) active off location 2" carbon steel flowline servicing KPK wells west of the release area. Based on observations, the impacts of the release appear to be historical in nature. Note: Integrity confirmation of the 2" active flowline should be completed by the operator via pressure testing.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Groundwater was observed in the excavation area.	maclarej	12/07/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100918	View east of excavation/ remediation area	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668066">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668066</a>
690100919	View NW of excavation and flowlines exposed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668067">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668067</a>
690100920	View of (2) flowlines exposed in excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668068">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668068</a>