

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2018

Submitted Date:

12/07/2018

Document Number:

689302553**FIELD INSPECTION FORM**

Loc ID 335454	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 9 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	<a href="#">all Piceance inspections</a>

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268492	WELL	PR	07/12/2012	GW	045-09266	EM 30-7 (B30NE)	PR
268493	WELL	PR	07/12/2012	GW	045-09267	EM 30-2 (B30NE)	PR
272098	WELL	PR	07/01/2018	GW	045-10023	BRYNILDSON 30-3 (B30NE)	PR
272107	WELL	PR	07/12/2012	GW	045-10025	BRYNILDSON 30-6 (B30NE)	PR
273518	WELL	PR	01/18/2005	GW	045-10257	BRYNILDSON 30-8 (B30NE)	PR
273554	WELL	PR	08/01/2012	GW	045-10259	BRYNILDSON 30-1 (B30NE)	PR

<b>General Comment:</b> This is a follow up inspection from Doc# 689302295. Required Corrective Action (s) items noted in previous inspections have been satisfied. Equipment inventory has not changed on location. Location is snow covered.
---

Inspected Facilities									
Facility ID:	268492	Type:	WELL	API Number:	045-09266	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	268493	Type:	WELL	API Number:	045-09267	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	272098	Type:	WELL	API Number:	045-10023	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	272107	Type:	WELL	API Number:	045-10025	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	273518	Type:	WELL	API Number:	045-10257	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	273554	Type:	WELL	API Number:	045-10259	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302554	Inspection photo 689302553	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668391">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668391</a>