

Inspection Photo (s)
Juhan Fee 26-94
API # 05-045-06023
Inspection # 689302573



Location Photo #1

Location Photo #2

Inspection Photo (s)
Juhan Fee 26-94
API # 05-045-06023
Inspection # 689302573



Location Photo #3 unmarked, unused flow line riser.

Location Photo #4, unmarked flow line riser.