

# Inspection Photos

12/10/2018

Operator: SMITH OIL PROPERTIES INC - 79905

Location ID: 313873

Inspection Doc. Number: 682504256

Morgan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the south end of the well location, facing northwest. Photo shows though pump unit appear to have been removed, no additional reclamation appears to have been conducted in accordance with 1004 rules



**Photo 2:** Photo taken from the south end of the well location, facing north. Photo shows though pump unit appear to have been removed, no additional reclamation appears to have been conducted in accordance with 1004 rules





**Photo 3:** Photo taken from the north end of the well location, facing southwest. Photo shows though pump unit appear to have been removed, no additional reclamation appears to have been conducted in accordance with 1004 rules; various trash debris, equipment and fence remains.





**Photo 4:** Photo taken from the west end of the well location, facing south. Photo shows straw wattle stormwater BMP previously documented remains on location and in disrepair.





**Photo 5:** Photo taken from the west end of the well location, facing east. Photo shows no reclamation activities appear to have been conducted in accordance with 1004 rules and corrective actions.





**Photo 6:** Photo taken from the west end of the well, facing east. Photo shows various trash debris, equipment and fence remaining on location.





**Photo 7:** Photo taken from the well. Photo shows riser remaining on location.





**Photo 8:** Photo taken from the access road, northeast of the well, facing northeast. Photo shows access road has not been reclaimed, and stormwater erosion degradation has been allowed to continued.





**Photo 9:** Photo taken from the east end of the pits, facing west. Photo shows pits have not been closed or reclaimed.





**Photo 10:** Photo taken from the east end of the pits, facing west. Photo shows pits have not been closed or reclaimed.





**Photo 11:** Photo taken from the east end of the pits, facing southwest. Photo shows pits have not been closed or reclaimed.





**Photo 12:** Photo taken from the west end of the battery location, facing northeast. Photo shows operator appears to have spread soil on top of the location, however, gravel has not been removed, compaction alleviation has not been conducted. Reclamation activities do not appear to have been conducted in accordance with 1004 rules and corrective actions.





**Photo 13:** Photo taken from the west end of the battery location, facing east. See comments under photo 12.





**Photo 14:** Photo taken from the west end of the battery location, facing south. See comments under photo 12.





**Photo 15:** Photo taken from the south end of the battery location, facing north. See comments under photo 12.





**Photo 16:** Photo taken from the south end of the battery location, facing west. Photo shows stormwater and reclamation issues have not been addressed.





**Photo 17:** Photo taken from the west end of the open pits, facing north. Photo shows no reclamation activities appear to have been conducted in accordance with 1004 rules and corrective actions.





**Photo 18:** Photo taken from the west end of the open pits, facing north. Photo shows no noxious weeds (Scotch thistle) have not been managed.





**Photo 19:** Photo taken from the south end of the well, facing north. Photo shows what appears to be contaminated soil has been stored on the south end of the well with insufficient stormwater and erosion control BMPs





**Photo 20:** Photo taken from the access road, facing south. Photo shows no reclamation activities appear to have been conducted in accordance with 1004 rules and corrective actions.