

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/10/2018

Submitted Date:

12/11/2018

Document Number:

691200931

**FIELD INSPECTION FORM**

Loc ID 319078 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
,		regulatory@foundationenergy.com	<a href="#">All Inspections</a>
Koehler, Bob		bob.koehler@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242846	WELL	SI	07/01/2018	ERIW	123-10637	SOONER UNIT 10-28	TA

**General Comment:**

This is a **SPILL / RELEASE** inspection.  
Location of spill / release is at Sooner 10-28 wellhead.  
(API: 05-123-10637).  
This is a UIC well.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	NE FIU supervisor was advised of a possible fluid spill / release near this well. I was asked to conduct an inspection. Upon my arrival I met with the company field operator who was on site. Site appeared to have less than 5 Bbls of what appeared to be water covering an area of approximately 25' x 10' around the wellhead. I did not observe any hydrocarbons that were released. Field operator stated that Foundation Energy regulatory dept. has been advised of the incident. Field operator advised that vac truck was enroute to help with cleanup.			
Corrective Action:				Date:

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 242846 Type: WELL API Number: 123-10637 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Wellhead appears to have a closed & plugged valve only. It appears disconnected from injection / flowline.  
Form 6 #401790142 dated 10/16/2018 indicates plans to repair or P&A this well.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
COGCC EPS staff has been notified and will follow-up on this incident.	evinsb	12/11/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200934	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4671679">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4671679</a>