

Construction and Stormwater Inspection

December 6, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP – 26580

Location ID: 449176

Inspection Document #: 674902302

Adams County, CO

NESE Section 28 T3S R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/3S65W28

Location ID: 449176



Photo 1. Photo taken from the entrance of the location off CR 21, facing North. Operator has installed vehicle tracking pad. BMPs in proper functioning condition at the time of this inspection.



Photo 2. Photo taken from the southeastern perimeter of the location, facing North.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/3S65W28

Location ID: 449176



Photo 3. Photo taken from the southeastern perimeter of the location, facing North. Photo illustrates a ditch and berm BMP that has been installed around the entire perimeter of the location in conjunction with other BMPs.



Photo 4. Photo taken from the eastern perimeter of the location, facing East. Operator is in the process of installing a sediment trap with a temporarily stabilized outlet.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/3S65W28

Location ID: 449176



Photo 5. Photo taken from the northeastern perimeter of the location, facing West. Photo illustrates filtrex wattles along the perimeter outside of the ditch and berm. Photo also illustrates the topsoil stockpile being stored along the eastern area and has been temporarily stabilized with equipment tracking. Also See comments under Photo 2.



Photo 6. Photo taken from the northeastern perimeter of the location, facing South. See comments under Photo 2.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/3S65W28

Location ID: 449176



Photo 7. Photo taken from the northwestern perimeter of the location, facing South. See comments under Photos 3 and 5.



Photo 8. Photo taken from the southeastern perimeter of the location, facing East. See comments under Photos 3 and 5.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/3S65W28

Location ID: 449176



Photo 9. Photo taken from the southwestern perimeter of the location, facing East. See comments under Photos 3 and 5.



Photo 10. Photo taken from the southwestern perimeter of the location, facing North. See comments under Photos 3 and 5.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/3S65W28

Location ID: 449176



Photo 11. Photo taken from northern perimeter of the location. Photo illustrates filter wattles along the perimeter that need to be overlapped.



Photo 12. Photo taken from northern perimeter of the location. Photo illustrates filter wattles along the perimeter that need to be trenched in over crop rows due to daylighting underneath.