

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2018

Submitted Date:

12/11/2018

Document Number:

690002888**FIELD INSPECTION FORM**
 Loc ID 454886 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454884	WELL	DG	07/19/2018		123-46761	Hurley H26-743	AO
454885	WELL	DG	07/13/2018		123-46762	Hurley H26-736	WO
454887	WELL	DG	07/08/2018		123-46763	Hurley H26-730	WO
454891	WELL	DG	06/29/2018		123-46765	Hurley H26-717	WO
454895	WELL	DG	07/03/2018		123-46769	Hurley H26-724	WO
454896	WELL	DG	06/23/2018		123-46770	Hurley H26-712	WO

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Sound walls, north east and south sides.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>454884</u>	Type: <u>WELL</u>	API Number: <u>123-46761</u>	Status: <u>DG</u>	Insp. Status: <u>AO</u>
Facility ID: <u>454885</u>	Type: <u>WELL</u>	API Number: <u>123-46762</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>454887</u>	Type: <u>WELL</u>	API Number: <u>123-46763</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>454891</u>	Type: <u>WELL</u>	API Number: <u>123-46765</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>454895</u>	Type: <u>WELL</u>	API Number: <u>123-46769</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>454896</u>	Type: <u>WELL</u>	API Number: <u>123-46770</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>

COGCC Comments

Comment	User	Date
Routine inspection.	carlilec	12/11/2018
Coiled rig drilling plugs on API 05-123-76761		
Operations are not impeded by previous fire related issues.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
690002889	Photo	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672202