

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2018

Submitted Date:

12/11/2018

Document Number:

681701134**FIELD INSPECTION FORM**
 Loc ID 335054 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bleil, Robert	970-329-4373	rbleil@ursaresources.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Holtz, Darin		darin.holtz@state.co.us	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
Lind, Jennifer	720-508-8362	jlind@ursaresources.com	All Inspections
Spencer, Stan		stan.spencer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459154	SPILL OR RELEASE	AC	11/20/2018		-	Castle Spring B Tank W1	EI

General Comment:

Joint field visit between COGCC, BLM, and operator in response to Spill/Release ID #459154. Work to delineate and remediate impacts associated with the subject spill is proceeding under approved Remediation Project #12168.

The subject spill resulted from a leak of an estimated 46 bbls into an unlined, metal SPCC from a production tank. On inspection date, production tanks had been removed, SPCC was partially disassembled, and flowline risers inside of tank battery had been exposed via hydroexcavation. Operator discussed spill/release discovery, sampling for delineation, and remediation options with surface owner (BLM) present.

Two temporary tanks have been brought to location to be used until the remediation is complete and new tanks can be installed. Operator has submitted a Form 04 Sundry Notice (doc #401856603) to document the presence of the temporary tanks on location.

Environmental**Spill/Remediation:**

Comment: [Per COA included on approved Site Investigation and Remediation Workplan \(doc #401855724\), submit eForm 27 Supplemental Report that includes an updated plan for horizontal and vertical delineation and remediation of impacts.](#)

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681701140	20181129 Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672313