

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2018

Submitted Date:

12/11/2018

Document Number:

689302585

FIELD INSPECTION FORM

Loc ID 311615 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCC.inspections@caerusoilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269700	WELL	PR	03/15/2004	GW	045-09399	SHIDELER 19-6D(F19)	PR
270078	WELL	PR	09/11/2004	GW	045-09451	HMU 19-2B (F19)	PR
270079	WELL	PR	03/15/2004	GW	045-09452	SHIDELER 19-7B (F19)	PR
270291	WELL	PR	11/29/2004	GW	045-09519	SHIDELER 19-6B (F19)	PR
270713	WELL	PR	09/16/2004	GW	045-09789	HMU 19-4D (F19)	PR
270714	WELL	PR	09/15/2004	GW	045-09788	HMU 19-3B (F19)	PR

General Comment:

[Routine Field Inspection.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:	
Comment:	1-800-791-7691
Corrective Action:	Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused 6" poly pipe on location near tank battery. see photo		
Corrective Action:	Comply with rule 603.f For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	01/11/2019

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Panel gates.		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	Panel gates.		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 6		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	2 tanks in a centralized battery.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Methanol tank
Other (Capacity)	1000 gallon
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Holes in secondary containment liner, see photos			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 01/11/2019

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>269700</u>	Type:	<u>WELL</u>	API Number:	<u>045-09399</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:		Date:							
Facility ID:	<u>270078</u>	Type:	<u>WELL</u>	API Number:	<u>045-09451</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:		Date:							
Facility ID:	<u>270079</u>	Type:	<u>WELL</u>	API Number:	<u>045-09452</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:		Date:							
Facility ID:	<u>270291</u>	Type:	<u>WELL</u>	API Number:	<u>045-09519</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:		Date:							
Facility ID:	<u>270713</u>	Type:	<u>WELL</u>	API Number:	<u>045-09789</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:		Date:							
Facility ID:	<u>270714</u>	Type:	<u>WELL</u>	API Number:	<u>045-09788</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:		Date:							

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Compaction				
Ditches						
Berms						
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302586	Inspection photo 689302586	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672510