

# Inspection Photos

Operator: BP America

API: 05-067-09492

Date: 11/14/2018



**Photo 1. View of the project area from the northeastern corner facing center.**





**Photo 2. View of the eastern project area from the northeastern corner facing southward. Interim reclamation area extends outside of fencing. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), western wheatgrass (*Thinopyron intermedium*), and sand dropseed (*Sporobolus cryptandrus*).**





**Photo 3. View of the western project area from the northwestern corner facing southward.**





**Photo 4. View of oil and gas tubing and what appears to be surface owner debris within the northeastern project area.**





**Photo 5. View of shotgun shells next to oil and gas equipment within the eastern project area.**





**Photo 6. View of cobble rundown within the southeastern project area. More shotgun shells are present in the foreground.**





**Photo 7. View of Russian knapweed (*Rhaponticum repens*) within the eastern project area.**





**Photo 8. View of rilling within the eastern project area.**