

Inspection Photos
Location Name: McWilliams 4-31
API: 05-081-06521



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Powder Wash Federal 28-7
API: 05-081-06605



Photo 1. Overview of location taken at entrance facing east.



Photo 2. Pit in tank battery.

Inspection Photos
Location Name: Powder Wash Federal 28-7
API: 05-081-06605



Photo 3. Stained soil at pump jack motor shed.



Photo 4. Stained soil at wellhead.

Inspection Photos
Location Name: Powder Wash Federal 28-7
API: 05-081-06605



Photo 5. Unmarked risers.



Photo 6. Weeds and vegetation around fired equipment.