

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/29/2018

Submitted Date:

12/12/2018

Document Number:

689801967

**FIELD INSPECTION FORM**

Loc ID 313000 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10407  
Name of Operator: ANTLER ENERGY LLC  
Address: PO BOX 104  
City: BAGGS State: WY Zip: 82321

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223250	WELL	PR	09/22/1985	OW	081-06614	PTASYNSKI 1X	PR

**General Comment:**

Routine follow up inspection. Snow cover limited scope of inspection, complete follow up will be performed in the spring.

**Inspected Facilities**

Facility ID: 223250 Type: WELL API Number: 081-06614 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Routine follow up inspection. Snow cover limited scope of inspection, complete follow up will be performed in the spring.</a>	waldrone	12/12/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802005	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4673966">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4673966</a>