

Inspection Photos

Operator: BP America

API: 05-067-06816

Date: 11/14/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing southeastward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), as well as weeds such as cheatgrass (*Bromus tectorum*). Vegetation is sparse and heavily grazed in areas and needs to be monitored.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of erosional channel within the western project area. Appears to be used as a cattle path.



Photo 5. View of musk thistles (*Carduus nutans*) within the western project area.