

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2018

Submitted Date:

12/12/2018

Document Number:

689702205**FIELD INSPECTION FORM**Loc ID 335618 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287572	WELL	PR	08/31/2010	GW	045-13001	UNOCAL-ENCANA 23D-4D	PR
288397	WELL	PR	08/31/2010	GW	045-13237	UNOCAL-ENCANA 24B-4D	PR
288398	WELL	PR	08/31/2010	GW	045-13236	UNOCAL-ENCANA 23B-4D	PR
288399	WELL	PR	08/31/2010	GW	045-13235	UNOCAL-ENCANA 24A-4D	PR
288400	WELL	PR	09/28/2007	GW	045-13234	UNOCAL-ENCANA 23A-4D	PR

General Comment:

Routine FIU General Field Inspection

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Capacity label is torn off of the tank.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	02/13/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign missing from well.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/13/2019

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	287572	Type:	WELL	API Number:	045-13001	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288397	Type:	WELL	API Number:	045-13237	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288398	Type:	WELL	API Number:	045-13236	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288399	Type:	WELL	API Number:	045-13235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288400	Type:	WELL	API Number:	045-13234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Ditches	Pass					
Compaction	Pass					
		Culverts	Pass			
Berms	Pass					
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702212	Inspection 689702205 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4674360