

Inspection Photos
Operator: Springdale Partners LLC
Lease: Springdale Storage 2
API #05-075-05861



1. Lease sign, Incorrect emergency contact number



2. Wellhead disconnected, Weeds

Inspection Photos
Operator: Springdale Partners LLC
Lease: Springdale Storage 2
API #05-075-05861



3. Separator in metal shed



4. Steel ring containment

Inspection Photos
Operator: Springdale Partners LLC
Lease: Springdale Storage 2
API #05-075-05861



5. Tank battery



6. Abandoned/Unmarked Risers/Flowlines