

**Inspection Photo (s)**  
**Clough RWF 532-18**  
**API # 05-045-12675**  
**Inspection # 6893026019**



**Location Photo #1**



**Location Photo #2**