

Inspection Photos

Location Name: Douglas Creek Unit-63S101W 5NWSW Pad

Location ID: #314293 Spill/Release ID: #459792

Inspection Date: December 12, 2018



Photo #1 – Overview of flowline integrity test configuration from south of excavation. Note stockpile of excavated material in foreground.



Photo #2 - View of additional excavated soil stockpile east of excavation. Note two capped PVC risers (monitoring wells) located south of excavation and east of stockpile.



Inspection Photos

Location Name: Douglas Creek Unit-63S101W 5NWSW Pad

Location ID: #314293 Spill/Release ID: #459792

Inspection Date: December 12, 2018



Photo #3 - View into excavation from southwest corner.



Photo #4 – Additional PVC riser (monitoring well) located between excavation and tank battery.



Inspection Photos

Location Name: Douglas Creek Unit-63S101W 5NWSW Pad

Location ID: #314293 Spill/Release ID: #459792

Inspection Date: December 12, 2018



Photo #5 – Operator was trucking in clean soil to backfill excavation on inspection date.



Photo #6 – Operator was instructed by COGCC Western Integrity Supervisor to cap unidentified 2" flowline that was exposed on east side of excavation.

