

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2018

Submitted Date:

12/13/2018

Document Number:

681701142

**FIELD INSPECTION FORM**

Loc ID 314293 Inspector Name: Arauza, Steven On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 1125 ESCALANTE DR  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	<a href="#">All Inspections</a>
Hale, Steven	(970) 290-2912	shale@utahgascorp.com	<a href="#">Environmental Specialist</a>
Spencer, Stan		stan.spencer@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Bleil, Robert	720-425-0303	inspections@utahgascorp.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459792	SPILL OR RELEASE	AC			-	Douglas Creek Unit #1 1	EI

**General Comment:**

COGCC environmental joint inspection with COGCC Western Integrity Inspector. Follow-up to Spill/Release Report (doc #401870624) corresponding to Spill/Release ID #459792.

Operator was onsite testing the repaired flowline for integrity on inspection date. Open excavation, adjacent to wellhead, measured approximately 6'x10'x4'. Additional, unidentified 2" flowline was exposed on east side of excavation. Operator was instructed to cap unidentified flowline by Integrity Inspector.

Three monitoring wells (capped, 2" PVC risers) observed south of excavation. See photos.

**Inspected Facilities**

Facility ID: 459792 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: Spill/Release ID #459792: Operator indicated that confirmation samples had been collected from the excavation by an environmental consultant and that the excavation would be partially backfilled with clean soil to prevent flowlines from freezing overnight. Impacted soil had been stockpiled on east and west sides of excavation. Operator indicated that soil would be hauled off for disposal.

Corrective Action: Submit eForm 19 Supplemental Spill/Release Report within 10 days of discovery date, per Rule 906.b spill reporting requirements. Comply with COAs listed on Initial Spill/Release Report (doc #401870624).

Date: 12/21/2018

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681701143	20181212 Field Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4675398">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4675398</a>