

Inspection Photos
Location Name: Richardson G #2
Spill/Release Point ID #459307



Vac truck preparing to expose pipeline along western edge of access road.



Hydro vac excavation to expose pipeline along eastern edge of access road.

Inspection Photos
Location Name: Richardson G #2
Spill/Release Point ID #459307



Exposed pipeline along eastern edge of access road.



Exposed 3" fiberglass pipelines within 12" casing sleeve.

Inspection Photos
Location Name: Richardson G #2
Spill/Release Point ID #459307



Potholed Williams pipeline in foreground.



Hydro vac truck preparing to expose pipelines along western edge of roadway.