

Inspection Photos
Operator Name: UTAH GAS
Location ID: 314293



Steel Flowline from injection pump to wellhead



90 Degree elbow where pin hole was found. Pin hole was on inside radius of elbow

Inspection Photos
Operator Name: UTAH GAS
Location ID: 314293



Flowline pine hole



90 Degree elbow where pin hole was found. Pin hole was on inside radius of elbow

Inspection Photos
Operator Name: UTAH GAS
Location ID: 314293



Inside picture of elbow



Inside picture of elbow