

Inspection Photo (s)
Couey 30-10A1
API # 05-045-07970
Inspection # 6893026039



Location Photo #1



Location Photo #2, Peeling tank label.

Inspection Photo (s)
Couey 30-10A1
API # 05-045-07970
Inspection # 6893026039



Location Photo #3, Debris on the west side of location.



Location Photo #4, Oil stained rock in battery containment.

Inspection Photo (s)
Couey 30-10A1
API # 05-045-07970
Inspection # 6893026039



**Location Photo #5, Unused concrete block
near wellheads.**