

Inspection Photo (s)
BJM 30-14
API # 05-045-09791
Inspection # 6893026041



Location Photo #1



Location Photo #2

Inspection Photo (s)
BJM 30-14
API # 05-045-09791
Inspection # 6893026041



Location Photo #3, Debris near wellheads.



Location Photo #4, Debris near separators.

Inspection Photo (s)
BJM 30-14
API # 05-045-09791
Inspection # 6893026041



Location Photo #5, Oil stained rock in battery containment.

Location Photo #6, Oil stained rock in battery containment.

Inspection Photo (s)
BJM 30-14
API # 05-045-09791
Inspection # 6893026041



**Location Photo #7, unmarked flow line riser
on East side of the containment.**