

Inspection Photo (s)
Dever 36-11
API # 05-045-07660
Inspection # 6893026047



Location Photo #1



Location Photo #2

Inspection Photo (s)
Dever 36-11
API # 05-045-07660
Inspection # 6893026047



Location Photo #3, Leaking plunger catch on well 36-10



Location Photo #4, Oil stained rock in battery containment.

Inspection Photo (s)
Dever 36-11
API # 05-045-07660
Inspection # 6893026047



Location Photo #5, Unused valves in battery.