

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2018

Submitted Date:

12/14/2018

Document Number:

689302639

FIELD INSPECTION FORM

Loc ID 335358 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 16 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCC.inspections@caerusoilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261630	WELL	PR	06/04/2002	GW	045-07970	COUEY 30-10A1 (O30NE)	PR
272414	WELL	PR	12/02/2004	GW	045-10075	COUEY 30-9 (O30NE)	PR
273477	WELL	PR	11/04/2004	GW	045-10252	COUEY 30-16 (O30NE)	PR
282075	WELL	PR	06/12/2006	GW	045-11619	COUEY 30-9C (O30NE)	PR
282076	WELL	PR	06/12/2006	GW	045-11618	COUEY 30-15B (O30NE)	PR

General Comment:

[Routine Field Inspection.](#)
[Location is snow covered.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank label peeling, can not read emergency contact numbers. see photos		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 01/14/2019
Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Oil stained rock in battery containment. see photo		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.		Date: 01/14/2019
Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Comply with Rule 603.f		Date: 01/14/2019
Type	UNUSED EQUIPMENT		
Comment:	Concrete block near wellheads.		
Corrective Action:	Comply with Rule 603.f		Date: 01/14/2019
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 5		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 5		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellheads.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	STEEL AST		
Comment:	1 tank is heated. 2 tanks in a centralized battery.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Methanol tank
Other (Capacity)	1000 gallon
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>261630</u>	Type:	<u>WELL</u>	API Number:	<u>045-07970</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	
Facility ID:	<u>272414</u>	Type:	<u>WELL</u>	API Number:	<u>045-10075</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	
Facility ID:	<u>273477</u>	Type:	<u>WELL</u>	API Number:	<u>045-10252</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	
Facility ID:	<u>282075</u>	Type:	<u>WELL</u>	API Number:	<u>045-11619</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	
Facility ID:	<u>282076</u>	Type:	<u>WELL</u>	API Number:	<u>045-11618</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302640	Inspection photo 689302640	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4677000