

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2018

Submitted Date:

12/14/2018

Document Number:

680404093

FIELD INSPECTION FORM

Loc ID 322495 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|----------------|-----------------------------|------------------------------------|
| Graves, Jim | 970-858-8550 | mrinc20@qwestoffice.net | Operations Manager |
| Reid, Jordan | (970) 563-4000 | maralextechjr@gmail.com | All Inspections |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 210630 | WELL | SI | 05/01/2012 | GW | 045-06386 | CALF CANYON-FEDERAL 26-1 | TA |

General Comment:

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Main | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|----------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|------------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Pipe fence | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------|--|--|-----------------|
| Equipment: | | | corrective date |
| Type: Flow Line | # | | |
| Comment: | Multiple 1" & 2" unused risers. Locked out/tagged out. | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 0 | | |
| Comment: | Equipment removed. | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 210630 Type: WELL API Number: 045-06386 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last MIT 12/31/2014.
Well TA longer than 6 months with no Form 4 submitted

Corrective Action: Submit Form 4 as directed by Rule 319.b

Date: 01/25/2019

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: _____ Pit ID: _____ Lat: 39.515717 Long: -108.740701

Reference Point: SE Other: _____ Length: 20 Width: 20

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: Fencing removed

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------------|---|
| 680404094 | Inspection photos 12/14/2018 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4677084 |