

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2018

Submitted Date:

12/14/2018

Document Number:

689302649

**FIELD INSPECTION FORM**

Loc ID 334967 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                 | Comment                                  |
|--------------|-------|---------------------------------------|--|
|              |       | COGCC.inspections@caerusoilandgas.com | <a href="#">all Piceance inspections</a> |

**General Comment:**

[Routine Field Inspection.](#)  
[Location is snow covered.](#)

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective ActionL |        |  | Date: |

Overall Good:

|                                  |                |  |             |
|----------------------------------|----------------|--|-------------|
| <b>Emergency Contact Number:</b> |                |  |             |
| Comment:                         | 1-800-791-7691 |  |             |
| Corrective Action:               |                |  | Date: _____ |

|                           |        |  |       |
|---------------------------|--------|--|-------|
| <b>Good Housekeeping:</b> |        |  |       |
| Type                      | DEBRIS |  |       |
| Comment:                  |        |  |       |
| Corrective Action:        |        |  | Date: |
| Type                      | TRASH  |  |       |
| Comment:                  |        |  |       |
| Corrective Action:        |        |  | Date: |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                                   |     |  |                 |
|-----------------------------------|-----|--|-----------------|
| <b>Equipment:</b>                 |     |  | corrective date |
| Type: Plunger Lift                | # 6 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Bird Protectors             | # 2 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Vertical Heated Separator   | # 5 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Horizontal Heated Separator | # 1 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Gas Meter Run               | # 1 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     | Date:       |
| Corrective Action: |          |                     |                     | Date:       |

| Contents                                   | # | Capacity | Type      | Tank ID | SE GPS |
|--|---|----------|-----------|---------|--------|
| CONDENSATE                                 | 2 | 500 BBLs | STEEL AST |         | ,      |
| Comment: 3 tanks in a centralized battery. |   |          |           |         |        |
| Corrective Action:                         |   |          |           |         | Date:  |

**Paint**

|                  |               |
|------------------|---------------|
| Condition        | Adequate      |
| Other (Content)  | Metahnol tank |
| Other (Capacity) | 1000 gallon   |
| Other (Type)     |               |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     | Date:       |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |
|--------------------|----|
| Yes/No             | NO |
| Comment:           |    |
| Corrective Action: |    |
| Date:              |    |

**Flaring:**

|                    |  |
|--------------------|--|
| Type               |  |
| Comment:           |  |
| Corrective Action: |  |
| Date:              |  |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Snow covered location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                   | URL   |
|--------------|-------------------------------|---|
| 689302650    | Inspection photo<br>689302650 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4677005">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4677005</a> |