

# Inspection Photos

Operator: BP Production

API: 05-067-09219

Date: 11/29/2018



**Photo 1. View of the project area from the southern corner facing center.**





**Photo 2. View of the southwestern project area from the southern corner facing northwestward. Revegetation is largely comprised of grasses such sideoats grama (*Bouteloua curtipendula*) and crested wheatgrass (*Agropyron cristatum*).**





**Photo 3. View of the northeastern project area from the northeastern corner facing northwestward.**





**Photo 4. View of diversion along the northeastern edge of the project area, appears to be functioning at this time.**





**Photo 5. View of erosional channel forming within the southeastern project area, around a cobble run-down.**