

Well Name : Sheffer Jack 1
API # : 069-05014



Photo 1: Wellhead.



Photo 2: Flowline off W side of wellhead with split in T.

Well Name : Sheffer Jack 1
API # : 069-05014



Photo 3: Close up of damaged T.



Photo 4: Disconnected line off E side of well looking SE towards house.

Well Name : Sheffer Jack 1
API # : 069-05014



Photo 5: Wellhead looking N.



Photo 6: Wellhead looking E.

Well Name : Sheffer Jack 1
API # : 069-05014



Photo 7: Wellhead looking S.



Photo 8: Wellhead looking W.

Well Name : Sheffer Jack 1
API # : 069-05014



Photo 9: Construction site on lot W of wellhead.



Photo 10: Wellhead center of picture looking SE from construction site.

Well Name : Sheffer Jack 1
API # : 069-05014



Photo 11: Abandoned steel cable.




Photo 12: Goggle Earth view marked up with legend.