

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2018

Submitted Date:

12/17/2018

Document Number:

685305674**FIELD INSPECTION FORM**Loc ID 385978 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 81701Name of Operator: STANDARD OIL PRODUCTION COAddress: P O BOX 4587City: HOUSTON State: TX Zip: 77210**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216626	WELL	PA	06/24/1931	GW	069-05016	HALL 1	SI

General Comment:

Inspection conducted with Orphaned Wells Program Engineer Mike Hickey.

This is an orphaned well inspection with emphasis on critical maintenance, verification and inventory of equipment, and identifying possible task required for potential well abandonment. As well is part of Orphaned Well Program all other open/required task for well/location abandonment remain open until completed and closed.

With no current operator corrective actions from previous field inspections have not been performed. Previous corrective actions will be evaluated and maybe converted into well abandonment task. Task will be prioritized and completed as part of well abandonment.

This orphaned well inspection included portions of May 2017 Flowline NTO to mark and inventory flowline risers. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable pictures.

Location

Lease Road:			
Type	Access		
comment:	There is no access road to well. Well is now located in driveway of residence with rock garden landscaping and landscaping block to create circle turn around in driveway.		
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	None.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 2		
Comment:	In use - 1" steel line from wellhead to domestic tap equipment. Line runs from regulator to detached shop building on SE side of home. Unused - 10" steel riser on W side of wellhead. (B) point unknown.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	216626	Type:	WELL	API Number:	069-05016	Status:	PA	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
<u>Comment:</u> <div>SI. Well is not P&A and is located on the W side of landowner residence in a rock garden turn around in the driveway. Well is plumbed into domestic tap equipment and was used in the past to supply gas to heat detached shop. Well is currently shut in.</div>									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Disturbed area for well was long ago converted into home site and driveway. Some dirt and gravel work will be required to repair driveway after plugging work is completed.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
As noted in 07/17/1996 inspection document number 500150820 well is located approximately 50' W of residence in what is now a rock garden turn around in the driveway. Well was used in the past to supply heating gas to a detached shop building on SE side of residence but is currently SI. Future tasks will include P&A of well. The only equipment items identified at time of inspection were the wellhead, steel riser, and (1) flowline. These items would generate task for removal/abandonment. Due to the proximity of the well to the house coordination with the landowner will be required. Additionally what would have been the disturbed area is now driveway, yard, and home. The area is level but will require a small working foot print to accomplish well plugging. Final reclamation work will primarily consist of possible grading and repair of driveway area.	stjohnw	12/17/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685305679	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4679750