

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2018

Submitted Date:

12/17/2018

Document Number:

685305675**FIELD INSPECTION FORM**
 Loc ID 385978 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 65888Name of Operator: OLDS OIL CORPORATION

Address: _____

City: DENVER State: CO Zip: _____**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216624	WELL	PA	04/13/1949	OW	069-05014	SHEFFER JACK 1	PR

General Comment:

Inspection completed with Orphaned Wells Program Engineer Mike Hickey.

This is an orphaned well inspection with emphasis on critical maintenance, verification and inventory of equipment, and identifying possible task required for potential well abandonment. As well is part of Orphaned Well Program all other open/required task for well/location abandonment remain open until completed and closed.

Primary reason for follow up inspection was to verify GPS data on wellhead and to use Magnetic Locator to evaluate flowline length/direction.

See link at end of report for path to downloadable pictures.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 216624 Type: WELL API Number: 069-05014 Status: PA Insp. Status: PR**Producing Well**Comment: Well currently used for domestic gas.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
The preliminary rough locate on W flowline indicated line does appear to continue W close to footer trenching and out into pasture. Construction site Landowner was home and provided information that the line had been uncovered while excavating for placement of the E footer. A determination has been made to abandon line as soon as possible. Flowline off the E side of wellhead does appear to turn SE towards residence on property and run to valves on W side of fencing. Line will be abandoned with appropriate notification provided to landowner. Orphaned Well Program Work Notice and contact information was left at residence.	stjohnw	12/17/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685305681	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4679841