

Inspection Photos
Location Name: Marlatt 12-22
Location ID: 320350



Photo#1 Pumpjack



Photo#2 Corrective Action: Wellhead leaking/Stained Soil

Inspection Photos
Location Name: Marlatt 12-22
Location ID: 320350



Photo#3 Corrective Action: Stained Soil