

# Inspection Photos

Operator: BP Production

API: 05-067-09705

Date: 11/28/2018



**Photo 1. View of the project area from the northwestern corner facing center.**



**Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is sparse and appears grazed. This needs to be monitored and revegetation installed if erosion worsens. Cattle exclusion may be needed.**



**Photo 3. View of the northern project area from the northwestern corner edge facing eastward.**



**Photo 4. View of the eastern project area from southeastern corner facing northward. Sparse revegetation within this area.**



**Photo 5. View of erosional channel approximately 36 inches wide and deep within the eastern portion of the project area.**



**Photo 6. View of another erosional channel within the eastern project area.**



Photo 7. View of musk thistle (*Carduus nutans*) within the eastern project area.