

Construction and Storm Water Inspection

December 11, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP – 26580

Location ID: 456540

Inspection Document #: 674902321

Arapahoe County, CO

NWSW Section 11 T4S R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/4S65W11

Location ID: 456540



Photo 1. Photo taken from the entrance of the location off CR 89, facing North. Operator has installed gravel potentially to limit tracking onto the county road. BMPs in proper functioning condition at the time of this inspection. BMPs in proper functioning condition at the time of this inspection.



Photo 2. Photo taken from the entrance of the location off CR 89, facing East. See comments from Photo 1.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/4S65W11

Location ID: 456540



Photo 3. Photo taken from the northwestern perimeter of the location, facing North. Photo illustrates a filterxx BMP that has been installed around the entire perimeter of the location in conjunction with other BMPs.



Photo 4. Photo taken from the northwestern perimeter of the location, facing East. Photo illustrates the start of a ditch and berm BMP that will be installed around the entire perimeter of the location in conjunction with other BMPs.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/4S65W11

Location ID: 456540



Photo 5. Photo taken from the southwestern perimeter of the location, facing East. See comments from Photo 3.



Photo 6. Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 3.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/4S65W11

Location ID: 456540



Photo 7. Photo taken from the southeastern perimeter of the location, facing North. See comments under Photos 3.



Photo 8. Photo taken from the southeastern perimeter of the location, facing West. Photo illustrates the topsoil stockpile being stored along the eastern area and has been temporarily stabilized with equipment tracking. Also see comments under Photo 3.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/4S65W11

Location ID: 456540



Photo 9. Photo taken from the northeastern perimeter of the location, facing East. Operator is in the process of installing a sediment trap with a temporarily stabilized outlet.



Photo 10. Photo taken from the northeastern perimeter of the location, facing North. See comments under Photos 9.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP – 26580/4S65W11

Location ID: 456540



Photo 11. Photo taken from the northeastern perimeter of the location, facing South. See comments under Photo 3.



Photo 12. Photo taken from the northeastern perimeter of the location, facing West. See comments under Photo 3.