

Interim Reclamation and Stormwater Inspection

December 19, 2018

Operator: SRC ENERGY INC- #10311

Location ID: 431367

Inspection Document #: 682404283

Weld County, CO

NWSW Section 2 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SRC /Vista Pad
Location ID: 431367



Photo 1. Photo taken from the northeast well pad, facing West. Appears the Operator has performed interim reclamation to reduce disturbance areas only needed for production operations. Interim areas will remain in-process as vegetation does not meet Rule 1003 standards.



Photo 2. Photo taken from the northeast well pad, facing Southwest. See comments under Photo 1.

Inspection Photos
Location Name: SRC /Vista Pad
Location ID: 431367



Photo 3. Photo taken from the southeast well pad, facing North. See comments under Photo 1.



Photo 4. Photo taken from the southwest well pad, facing North. See comments under Photo 1.

Inspection Photos
Location Name: SRC /Vista Pad
Location ID: 431367



Photo 5. Photo taken from the southwest interim area, facing North. Photo illustrates germination of desirable species; however, germination was not uniform throughout the interim area which is not reflective of reference area vegetative levels. Operator may need to perform additional reclamation activities along the southern interim area.



Photo 6. Photo taken from the southwest interim area, facing East. See comments under Photo 5.

Inspection Photos
Location Name: SRC /Vista Pad
Location ID: 431367



Photo 7. Photo taken from the southern interim area, facing West. See comments under Photo 5.



Photo 8. Photo taken from the southern interim area, facing Northwest. See comments under Photo 5.

Inspection Photos
Location Name: SRC /Vista Pad
Location ID: 431367



Photo 9. Photo taken from the northern interim area, facing South. The north/northeast interim area appears to meet Rule 1003 standards.



Photo 10. Photo taken from the northeastern interim area, facing South. The left half of the photo illustrates the reference area (Smooth brome) and the right half of the photo illustrates the interim area that appears to meet Rule 1003 standards.

Inspection Photos
Location Name: SRC /Vista Pad
Location ID: 431367



Photo 11. Photo taken from the entrance of the location, facing East. Vehicle tracking BMP appears to be in proper functioning condition.



Photo 12. Photo taken from the entrance of the location, facing South. No observed track out issues.