

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 244457 Type: WELL API Number: 123-12252 Status: PR Insp. Status: PA

Workover

Comment: Rig crew was in the process of rigging up at time of arrival. Crew pulled tubing, then set CIBP (2 sx cement) above Jsand Perfs. Set CIBP above Niobrara and codell perfs. Crew set retainer perforated holes and squeezed cement.
Wind was blowing North East all day during operations.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT