

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/12/2018

Submitted Date:
12/13/2018

Document Number:
681701142

FIELD INSPECTION FORM

Loc ID 314293 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	All Inspections
Hale, Steven	(970) 290-2912	shale@utahgascorp.com	Environmental Specialist
Fischer, Alex		alex.fischer@state.co.us	
Bleil, Robert	720-425-0303	inspections@utahgascorp.com	All inspections
Murray, Richard		g.richard.murray@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459792	SPILL OR RELEASE	AC			-	Douglas Creek Unit #1 1	EI

General Comment:

COGCC environmental joint inspection with COGCC Western Integrity Inspector. Follow-up to Spill/Release Report (doc #401870624) corresponding to Spill/Release ID #459792.

Operator was onsite testing the repaired flowline for integrity on inspection date. Open excavation, adjacent to wellhead, measured approximately 6'x10'x4'. Additional, unidentified 2" flowline was exposed on east side of excavation. Operator was instructed to cap unidentified flowline by Integrity Inspector.

Three monitoring wells (capped, 2" PVC risers) observed south of excavation. See photos.

Inspected Facilities

Facility ID: 459792 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Spill/Release ID #459792: Operator indicated that confirmation samples had been collected from the excavation by an environmental consultant and that the excavation would be partially backfilled with clean soil to prevent flowlines from freezing overnight. Impacted soil had been stockpiled on east and west sides of excavation. Operator indicated that soil would be hauled off for disposal.

Corrective Action: Submit eForm 19 Supplemental Spill/Release Report within 10 days of discovery date, per Rule 906.b spill reporting requirements. Comply with COAs listed on Initial Spill/Release Report (doc #401870624).

Date: 12/21/2018

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401874064	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4675400
681701143	20181212 Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4675398