

# Inspection Photos

Operator: BP Production

API: 05-067-10010

Date: 11/29/2018



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is sparse and appears grazed. This needs to be monitored and revegetation installed if vegetation is not increasing. Livestock exclusion may be needed.**



**Photo 3. View of seedlings becoming established on well pad berms.**



**Photo 4. View of wattle debris that needs to be removed.**



**Photo 5. View of area upstream of culvert, no down-cutting observed.**



**Photo 6. View of area downstream of culvert, erosional downcutting up to 1.5 feet deep and 3 feet wide observed. Stabilization is needed.**