

Inspection Photos
Operator Name: Laramie Energy LLC
Location ID: 334529



Spill area, Flowline with leak travels to the tanks on right side

Inspection Photos
Operator Name: UTAH GAS
Location ID: 314293



Flowlines pictured in excavation



Flowline with section cut out where leak was found

Inspection Photos
Operator Name: Laramie Energy LLC
Location ID: 334529



**Flowlines in exaction trench with 2 other
Abandoned flowlines discovered when digging.
They were open ended**

Inspection Photos
Operator Name: Laramie Energy LLC
Location ID: 334529



Flowline pictured with pinhole



Flowline cut section with pinhole