

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2018

Submitted Date:

12/20/2018

Document Number:

693200204**FIELD INSPECTION FORM**

Loc ID 334529 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Bankert, Wayne	(970) 683-5419	cogccnotifications@laramie-energy.com	All inspections
Arauza, Steven		steven.arauza@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459854	SPILL OR RELEASE	AC	12/13/2018		-	McDaniel 2-9	EG

General Comment:

[Engineering Integrity Inspection performed on December 14, 2018. In response to initial form 19 spill report Doc #401873094](#)

Inspected FacilitiesFacility ID: 459854 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Dump Line	1 of Lines	
----	-----------------	------------	--

Flowline DescriptionFlowline Type: Dump LineSize: 2"Material: Carbon SteelVariance: NoAge: 10-15 YrsContents: Produced WaterIntegrity SummaryFailures: External CorrosionSpills: YesRepairs Made: NoCoatings: Yes ExternalH2S: No

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Flowlines were exposed at time of inspection. Section of pipe was cut out of flowline.Corrective Action: Establish root cause of the failure and discuss measures that will be taken to prevent reoccurrence on the form 19 subsequent.Date: 01/01/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200205	Laramie	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4684606