

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2018

Submitted Date:

12/14/2018

Document Number:

680404091**FIELD INSPECTION FORM**Loc ID 311533 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Graves, Jim	970-858-8550	mrinc20@qwestoffice.net	Operations Manager
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210378	WELL	TA	02/01/2017	GW	045-06134	CALF CANYON 23-4	PA
210580	WELL	SI	02/01/2017	GW	045-06336	CALF CANYON 23-4A	TA

**General Comment:**

**Location****Lease Road:**

Type	Main		
comment:			
Corrective Action		Date:	
Type	Access		
comment:	Private		
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	pipe fence		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Flow Line	#		
Comment:	All equipment removed. Flowline risers locked out tagged out.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 210378 Type: WELL API Number: 045-06134 Status: TA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well plugged and abandoned 2/3/2018.  
Form 6(s) submitted 3/6/2018. In process.  
Cut off wellhead noted in previous inspection removed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 210580 Type: WELL API Number: 045-06336 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Form 42 (Notice of MIT) doc#401505167 submitted 1/6/2018. No MIT performed.  
No current MIT on record or delinquent as required by Rule 326.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan. Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401875776	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676978">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676978</a>
680404092	Inspection photos 12/14/2018	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676972">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676972</a>