

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2018

Submitted Date:

12/14/2018

Document Number:

688800395**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 1375Name of Operator: LINDE INCAddress: 200 SOMERSET CORP BLVD #7000City: BRIDGEWATER State: NJ Zip: 07083**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Hughes, Jerrod	970-565-7021	jerrod.hughes@linde.com	<a href="#">SW Inspection Reports</a>
Jardine, Jennifer		jjardine@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458267	SPILL OR RELEASE	AC	11/09/2018		-	Airco #2 Natural Gas Well	EI

**General Comment:**

On December 12, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Linde Airco #2 Natural Gas Well Spill/Release Point ID #458267. For the most recent field inspection report of this facility, please refer to document #688800349. This was a joint inspection with BLM staff members Jennifer Jardine and Tanner Nygren.

Inspected Facilities									
Facility ID:	458267	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: Please refer to Spill/Release Point ID #458267 in the COGIS database for more information regarding this release. Per COA on supplemental spill report document #401811750, the operator shall submit a Form 27 Site Investigation and Remediation Workplan.

Corrective Action: Contact COGCC EPS staff regarding Rule 906.c.

Date: 12/14/2018

Reportable: YES

GPS: Lat 37.352786

Long 108.782793

Proximity to Surface Water: 5500

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Waste Management:**

Type Management Condition GPS (Lat) (Long)

Piles Adequate

Comment: Impacted material has been loaded by hand into totes that will reportedly be airlifted from the canyon on 12/18/18.

Corrective Action: Provide waste transportation and final disposition information in accordance with 907.b.2 for all E&P waste transported off site.

Date: 12/21/2018

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
On December 12, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Linde Airco #2 Natural Gas Well Spill/Release Point ID #458267. For the most recent field inspection report of this facility, please refer to document #688800349. This was a joint inspection with BLM staff members Jennifer Jardine and Tanner Nygren. The focus of this field inspection was from below the cliff face to the release end point in the wash. Hand crews were loading 5 gallon buckets with impacted material and placing it into totes to be airlifted out of the canyon for disposal. The operator shall provide a Form 27 Site Investigation and Remediation Workplan detailing ongoing and proposed remediation activities.	hughesjo	12/14/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401874931	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676241">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676241</a>
688800396	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676238">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676238</a>

