

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2018

Submitted Date:

12/19/2018

Document Number:

688303238**FIELD INSPECTION FORM**

Loc ID 455607 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 81490Name of Operator: ST CROIX OPERATING INCAddress: P O BOX 13799City: DENVER State: CO Zip: 80201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Savio, N Renee	(303) 216-2878	nrsavio@aol.com	
Melnychenko, Paul	(303) 489-9298	stcroixexp@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455608	WELL	DG	12/10/2018		121-11079	JACK CREEK 2	DG

**General Comment:**Surface Cementing Inspection

**Inspected Facilities**

Facility ID: 455608 Type: WELL API Number: 121-11079 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: WW Rig 20 Pusher/Rig Manager: John  
 Permit Posted: Yes Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: NO Disposal Location: \_\_\_\_\_

**Comment:** BOP test 750 psi/190 psi  
PTD 503', TD 510', 8 5/8"

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Cement****Cement Contractor**

Contractor Name: QES Contractor Phone: \_\_\_\_\_

**Surface Casing**

Cement Volume (sx): 300 Circulate to Surface: YES  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

**Intermediate Casing**

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

**Production Casing**

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

**Plugging Operations**

Depth Plugs(feet range): \_\_\_\_\_ Cement Volume (sx): \_\_\_\_\_  
 Good Return During Job: \_\_\_\_\_ Cement Type: \_\_\_\_\_

**Comment:** Fresh water from Akron, CO  
30 bbls displacement  
10 bbls back

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass			Covering Materials	Pass	
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688303265	St Croix Jack Creek 2 rig lights	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685150">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685150</a>
688303266	St Croix Jack Creek 2 cementers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685151">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685151</a>