

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2018

Submitted Date:

12/21/2018

Document Number:

689302719

**FIELD INSPECTION FORM**

Loc ID 334780 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211582	WELL	PR	09/14/1999	GW	045-07343	BERNKLAU RMV 116-33	PR
289642	WELL	PR	03/07/2007	GW	045-13824	HILLTOP 2F2 RANCH LLC RWF 22-33	PR
289643	WELL	PR	03/07/2007	GW	045-13823	HILLTOP 2F2 RANCH LLC RWF 422-33	PR
289644	WELL	PR	03/07/2007	GW	045-13822	HILLTOP 2F2 RANCH LLC RWF 312-33	PR
289645	WELL	PR	03/07/2007	GW	045-13821	HILLTOP 2F2 RANCH LLC RWF 12-33	PR
289646	WELL	PR	03/07/2007	GW	045-13820	HILLTOP 2F2 RANCH LLC RWF 13-33	PR
456920	Domestic Tap	AC	08/28/2018		-	Domestic Tap 33NESW	AC
456921	Domestic Tap	AC	08/28/2018		-	Domestic Tap 33NESW	AC

**General Comment:**

[Routine Field Inspection.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Emergency Contact Number:</b>			
Comment:	1-970-285-9377		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panel fence.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panel fence.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	2 chemical units at wellheads.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	2 tanks in a centralized battery.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:


**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	211582	Type:	WELL	API Number:	045-07343	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289642	Type:	WELL	API Number:	045-13824	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289643	Type:	WELL	API Number:	045-13823	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289644	Type:	WELL	API Number:	045-13822	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289645	Type:	WELL	API Number:	045-13821	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289646	Type:	WELL	API Number:	045-13820	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	456920	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC
<b>Workover</b>									
Comment:	"No CA until 2019 Submit an eForm 44 Flowline Report per Rule 1101.b."								
Corrective Action:					Date:				



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Culverts				
		Gravel				
		Compaction				
Ditches						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302720	Inspection photo 689302720	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686040">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686040</a>