

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2018

Submitted Date:

12/20/2018

Document Number:

693200204

**FIELD INSPECTION FORM**

Loc ID 334529 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1400  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	cogccnotifications@laramie-energy.com	<a href="#">All inspections</a>
Arauza, Steven		steven.arauza@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459854	SPILL OR RELEASE	AC	12/13/2018		-	McDaniel 2-9	EG

**General Comment:**

[Engineering Integrity Inspection performed on December 14, 2018. In response to initial form 19 spill report Doc #401873094](#)

**Inspected Facilities**

Facility ID: 459854 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

**Flowline**

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: No Age: 10-15 Yrs Contents: Produced Water

Integrity Summary

Failures: External Corrosion Spills: Yes Repairs Made: No  
 Coatings: Yes External H2S: No Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Flowlines were exposed at time of inspection. Section of pipe was cut out of flowline.

Corrective Action: Establish root cause of the failure and discuss measures that will be taken to prevent reoccurrence on the form 19 subsequent.

Date: 01/01/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401883295	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4684610">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4684610</a>
693200205	Laramie	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4684606">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4684606</a>